

# FITNESS CERTIFICATE

To be filed by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer Aruna V Assistant Engineer
2. Name of the School Viswadeepthi English medium school
3. Location with name of Education District/ Sub. District Kattakada
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.  
multistoried - 3 floor (7 rooms x 3 floor)  
including office room  
49 x 8.55 x 3.71m  
49 x 8.55 x 3.71m  
49 x 8.55 x 3.71m
5. Period for which the certificate is issued 2023-2024
6. Nature of defects, if any  
a) Foundation and basement  
b) Superstructure  
c) Doors and Windows  
d) Wood work wrought and put up  
e) Roof  
f) Flooring  
g) Miscellaneous (Cracks, etc.)  
Nil
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes Sound under normal weather loading and wind conditions


Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 18/5/23 and found to be fit / unfit to conduct classes, for the period 2023-24 for the reasons stated above.

Place: Kattakada

Date: 23/5/23



(Seal)

[Signature]

Assistant Engineer

MANAGER  
VISWA DEERTHI E.M. SCHOOL  
KATTAKADA, TVM. 695572

[Signature]