## CERTIFICATE

To be fiiled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

	type .	1 1
1.	Name of the Officer	Aryna, V Assistant Engineer
2.	Name of the School	Viscus deepths English Medium School
3.	Location with name of Education District/ Sub. District	tattatada.
4.	Classification of Building as specified in column 4 of the application for fitness certificate and size.	Multi Storaged - 3 Floor Preluding Joffice Room
		494 (18.55 x3. 71 h)
		49x 8.55x3.71m
		49 x 8,55 x3.71.7
5.	Period for which the certificate is issued	2025 - 2026
6.	Nature of defects, if any	
	a) Foundation and basement	
	b) Superstructure	
	c) Doors and Windows	
	d) Wood work wrought and put up	
	e) Roof	4.9
	f) Flooring	
	g) Miscellaneous (Cracks, etc.)	
7.	Any major defects noticed which will render the building unsafe in any manner	
		V26
8.	Whether maintenance works have been done properly	Sand under x formal loading worther
9.	Whether the structure is sound or not for conducting classes  Note: 1. The stability of the structure should be examined a exposure of flood etc. 2. Any additional observations if d separately with this certificate.	dso with reference to location, altitude, intensity of wind,
	CERTIFI	CATE
		24 Colons
	certified that the school building was inspected by me	e on 07/03/2025 and
fou	certified that the school building was inspected by mound to be fit / unfit to conduct classes, for the period	2025 - 2026, for the
rea	asons stated above.	
Pla	ace: 7.9.49.70.09 695572 695572 695572 (Settle :	salstant Engine Panchayat 2
500/	MANAGER SCHOOL  MANAGER SCHOOL  MANAGER SCHOOL  MANAGER SCHOOL  MANAGER SCHOOL	AASSISTANT Ention chayal  AASSISTANT Ention chayal  AASSISTANT Ention chayal  AASSISTANT Ention chayal